

# Oil Field Environmental Incident Summary

**Incident:** 20140523065612      **Date/Time of Notice:** 05/23/2014 06:56

**Responsible Party:** EOG RESOURCES, INC.

**Well Operator:** EOG RESOURCES, INC.

**Well Name:** GRAIL 200-02 SWD

**Field Name:** SPOTTED HORN

**Well File #:** 90245

**Date Incident:** 5/22/2014      **Time Incident:** 09:00

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 150

**Rng:** 95

**Sec:** 2

**Qtr:** SE SE

**Location Description:**

**Submitted By:** Keith Kallberg

**Received By:**

**Contact Person:** Keith Kallberg  
600 17TH ST STE 1000N  
DENVER, CO 80202

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	15	Barrels	15	Barrels	15	barrels
Other						

**Description of Other Released Contaminant:**

**Inspected:**      **Written Report Received:** 10/26/2015      **Clean Up Concluded:** 5/23/2014

**Risk Evaluation:**

N/A

**Areal Extent:**

Inside & outside the pump building on the west side.

**Potential Environmental Impacts:**

N/A

**Action Taken or Planned:**

SWD operator was able to close the actuator valve stopping the release, actuator valve will be repaired. Vac truck was used to remove the free standing fluid, hotoiler & vac truck will work together to flush the area 2 x with fresh water & remove

**Wastes Disposal Location:** Grail SWD

**Agencies Involved:**

**Updates**

---

**Date:** 5/23/2014    **Status:** Reviewed - Assigned to Other Agency

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release at an SWD remained on location. NDIC retains oversight.